



Ref. No.	Part No.	Description	Q'ty /Tool	Ref. No.	Part No.	Description	Q'ty /Tool	Ref. No.	Part No.	Description	Q'ty /Tool
1C	SPC3510001C	10x330MM Belt (#80)	1	18	SPC3510018	Housing	1	39	SPC3510040	Tension Bar	1
1D	SPC3510001D	10x330MM Belt (#100)	1	19	SPC3510019	Ball Bearing #628ZZ	1	40	SPC3510041	Spring	1
1E	SPC3510001E	10x330MM Belt (#120)	1	20	SPC3510020	End Plate	1	41	SPC3510042	Lever Pin	1
2	SPC3510002	Idler Pulley 10 Sup Ass'y	1	21	SPC3510021	Spacer 8x11x3	1	42	SPC3510043	Lever Pin	1
4	SPC3510004A	Idler Pulley Shaft 10	1	22	SPC3510022	Key 3x3x10	1	43	SPC3510044	Hex. Wrench Key 4.0MM	1
5	SPC3510005A	Bracket 10	1	23	SPC3510023	Cap	1	44	SPC3510044A	Hex. Wrench Key 1.5MM	1
6	SPC3510006	Tension Bar 10	1	24	SPC3510024	Ball Bearing #607ZZ	1	45	SPC3510045A	O-Ring 2.6x35	1
7	SPC3510007	Hex. Socket Headress Set Screw 3x6	1	25	SPC3510025	End Plate	1	46	SPC3510046	Rubber	1
8	SPC3510008	Cross Recessed Flat Head Machine Screw 3x8	1	26	SPC3510026	Cylinder	1	47	SPC3510047	Ball Bearing	2
9	SPC3510009	Spring 1.0x7.2x6.5	1	27	SPC3510027	Blade	4	48	SPC3510048	Washer	1
10	SPC3510010	Spring Pin 3x10	2	28	SPC3510028	Rotor	1	49	SPC3510049	O-Ring	1
11	SPC3510011	Spring 3.1x1x41L	1	29	SPC3510029	Throttle Lever	1	50	SPC3510050	Muffler	1
12	SPC3510012	Shoe 10	1	30	SPC3510030	Lever Pin	1				
13	SPC3510013	Cross Receptor Pan Heac Machine Screw 4x8	1	31	SPC3510031	Valve Body	1				
14	SPC3510014	Guard	1	32	SPC3510032	O-Ring P7	1				
15	SPC3510015	Hex. Socket Head Bolt	1	33	SPC3510033	O-Ring P5	1				
16	SPC3510016	Hexagon Nut MG	1	34	SPC3510034	Valve Stem	1	RK	SPC35100RK	Repair Kit Ref. No.-- 19, 24, 27(x4), 45	
17	SPC3510017	Drive Pulley	1	35	SPC3510035	O-Ring 3.6x2.4	1				
				36	SPC3510036	O-Ring 3.6x2.4	1				
				37	SPC3510037	Valve Spring	1	SK	SPC35100SK	Service Kit Ref. No.-- 9, 11, 32, 33, 35, 36, 40	
				38	SPC3510038	Deflector	1				
				39	SPC3510039	Air Inlet	1				